Appendix 36

Meadowbank AWAR Freshet Inspections

Inspection Sheet 1: Stream Erosion Inspection Sheet

Date: 2018-06-05
Field Crew: Robin Allard
Weather: Sunny
General Description: Snow in all bridge stream.

Date	Station ID	Km	Flow? (Y/N)	Erosional Concerns	Visible Turbidity	Photo #	Comment:
2018-06-05	9	83	No	No	still snow		
2018-06-05	8	79	No	No	still snow		
2018-06-05	7	73	No	No	still snow		
2018-06-05	6	69	No	No	still snow		
2018-06-05	5	63	No	No	still snow		
2018-06-05	4	49	No	No	still snow		
2018-06-05	3	23	No	No	still snow		
2018-06-05	2	11	No	No	still snow		
2018-06-05	1	9	No	No	still snow		

Inspection Sheet 1: Stream Erosion Inspection Sheet

Date: 2018-06-08
Field Crew: Robin Allard
Weather: Sunny
General Description: Freshet ongoing

Date	Station ID	Km	Flow? (Y/N)	Erosional Concerns	Visible Turbidity	Photo #	Comment:
2018-06-08	9	83	No	No	still snow	ID-9	
2018-06-08	8	79	No	No	still snow	ID-8	
2018-06-08	7	73	No	No	still snow	ID-7	
2018-06-08	6	69	No	No	still snow	ID-6	
2018-06-08	5	63	yes	No	no	ID-5	surface flow
2018-06-08	4	49	yes	No	no	ID-4	surface flow
2018-06-08	3	23	No	No	still snow	ID-3	
2018-06-08	2	11	yes	No	no	ID-2	
2018-06-08	1	9	No	No	still snow	ID-1	

Inspection Sheet 1: Stream Erosion Inspection Sheet

Date: 2018-06-29
Field Crew: Fanny Laporte
Weather: Sunny
General Description: all snow melted, no eccessive flow, no area of concern

Date	Station ID	Km	Flow? (Y/N)	Erosional Concerns	Visible Turbidity	Photo #	Comment:
2018-06-29		9	Y	No	No	Y	
2018-06-29		17	Y	No	No	Y	
2018-06-29		23	Y	No	No	Y	
2018-06-29		49	Y	No	No	Y	
2018-06-29		62	Y	No	No	Y	
2018-06-29		69	Y	No	No	Y	
2018-06-29		73	Y	No	No	Y	
2018-06-29		76	N	No	No	Y	
2018-06-29		84	Y	No	No	Y	
	Pictures identifed in file: P:\Environment\INSPECTIONS AND FORMS\2018\Meadowbank\AWAR Turbidity Erosion\06-JUN\2018-06-29						

Inspection Sheet 1: Stream Erosion Inspection Sheet

Date: 2018-07-06
Field Crew: MBA/MOR
Weather: Cloudy, sporadic rain
General Description: all snow melted, no excessive flow, no area of concern

Date	Station ID	Km	Flow? (Y/N)	Erosional Concerns	Visible Turbidity	Photo #	Comment:
2018-07-06		9	Y	No	No	Y	
2018-07-06		17	Y	No	No	Y	
2018-07-06		23	Y	No	No	Y	
2018-07-06		49	Y	No	No	Y	
2018-07-06		62	Y	No	No	Y	
2018-07-06		69	Y	No	No	Y	
2018-07-06		73	Y	No	No	Y	
2018-07-06		76	N	No	No	Y	
2018-07-06		84	Y	No	No	Y	
	Pictures identifed in file: P:\Environment\INSPECTIONS AND FORMS\2018\Meadowbank\AWAR Turbidity Erosion\07-JUL\2018-07-06						

Inspection Sheet 1: Stream Erosion Inspection Sheet

Date: 2015-07-27

Field Crew: PATRICK AHERN

Weather: Clear skies, DRY, Not windy

General Description: All snow melted, No Area of concern

Date	Station ID	km	Flow? (Y/N)	Erosional Concerns	Visible Turbidity	Photo #	Comment:
7/27/18		9	Y	N	N	28-30	
"		17	Y	N	N	31-34	
"		23	Y	N	N	35-38	
"		49	Y	N	N	39-40	
"		62	Y	N	N	42-43	
"		69	Y	N	N	44-47	
"		73	Y	N	N	48-49	
"		76	N	N	N	50-51	
"		84	Y	N	N	52-53	